

MICRONLINE Ø 20

■ POS 1

SLAB THICKNESS [INCHES OR MM]

12- 20-30-40

RPM (MIN-MAX)

6.000—6.500

STOCK REMOVAL [INCHES OR MM]

TO SHAPE 0,3 MAX

FEEDING SPEED [INCHES/MINUTE OR MM/MINUTE]

400-600



SEGMENTED

■ POS 2

SLAB THICKNESS [INCHES OR MM]

12- 20-30-40

RPM (MIN-MAX)

6.000—6.500

STOCK REMOVAL [INCHES OR MM]

0,2-0,3

FEEDING SPEED [INCHES/MINUTE OR MM/MINUTE]

800-1.000



SEGMENTED

■ POS 3

SLAB THICKNESS [INCHES OR MM]

12- 20-30-40

RPM (MIN-MAX)

6.000—6.500

STOCK REMOVAL [INCHES OR MM]

0,15

FEEDING SPEED [INCHES/MINUTE OR MM/MINUTE]

800-1.000



SEGMENTED

MICRONLINE Ø 20

■ POS 4

SLAB THICKNESS [INCHES OR MM]

12- 20-30-40

RPM (MIN-MAX)

5.800

STOCK REMOVAL [INCHES OR MM]

0,10

FEEDING SPEED [INCHES/MINUTE OR MM/MINUTE]

800-1.000



SEGMENTED

■ POS 5-6-7

SLAB THICKNESS [INCHES OR MM]

12-20-30-40

RPM (MIN-MAX)

3.300-3.800

STOCK REMOVAL [INCHES OR MM]

0,03-0,05

PRESSURE

FEEDING SPEED [INCHES/MINUTE OR MM/MINUTE]

750-1.000



EXPRESS POLISHING