

<b>Characteristic</b>	<b>Surface Bonder Zero</b>
Working Time	9–14 Minutes
Fixture Time	20–30 Minutes
Operating Temperature	60°F–85°F (18°C–30°C) * Use at temperatures below 55°F(12°C) or above 90°F(32°C) may cause incomplete cure, yellowing and poor bonding strength.
Viscosity – Adhesive	20,000–50,000 cps
Viscosity – Activator	700–2,000 cps
Color – Adhesive	Various
Color – Activator	Colorless / Translucent
Mix Ratio	10:1
Tensile Strength – Natural Stone	>4,000 PSI / Substrate Failure
Tensile Strength – Quartz	>4,000 PSI / Substrate Failure
Shelf Life	2 Years