

Phone: 816.421.3000 | Fax: 816.421.3122 | www.westix.net

# MATERIAL SAFETY DATA SHEET HOT MELT ADHESIVES

Prepared Date: 02/14/2014

#### **SECTION I**

MANUFACTURED BY: Western American, Inc

1518 Taney Street

North Kansas City, MO 64116

TELEPHONE: 816-421-3000 CONTACT: Rick Hennig

PRODUCT CLASS: Hot Melt Adhesive

MANUFACTURER'S CODES: **ST11** 

NON DOT REGULATED

# **SECTION II - HAZARDOUS INGREDIENTS**

N/A

# SECTION III - PHYSICAL DATA

BOILING POINT - N/A SPECIFIC GRAVITY - 0.92 VAPOR PRESSURE - N/A MELTING POINT - 160 - 230 VAPOR DENSITY - N/A EVAPORATION RATE - N/A

SOLUBILITY IN WATER - INSOLUBLE

APPEARANCE AND ODOR - CLEAR AND LOW ODOR

# SECTION IV - FIRE AND EXPLOSION HAZARD DATA

DOT CATEGORY - NON FLAMMABLE

FLASH POINT - 450F

EXTINGUISHING MEDIA - CO2

SPECIAL FIRE FIGHTING PROCEDURES - NONE UNUSUAL FIRE AND EXPLOSION HAZARDS - NONE

## SECTION V - HEALTH HAZARD DATA

MAIN ROUTE OF ENTRY - INHALATION, PROVIDE ADEQUATE VENTILATION TARGET ORGANS - NONE HEALTH HAZARDS (ACUTE AND CHRONIC) - NONE CONTACT WITH MOLTEN MATERIAL WILL CAUSE THERMAL BURNS TO SKIN AND EYES



Phone: 816.421.3000 | Fax: 816.421.3122 | www.westix.net

#### FIRST AID:

# COOL AFFECTED AREA IMMEDIATELY, OBTAIN MEDICAL ASSISTANCE, DO NOT ATTEMPT TO REMOVE COOLED ADHESIVE FROM SKIN, AS IT WILL SEVERELY DAMAGE SKIN

# **SECTION VI - REACTIVITY DATA**

STABILITY - STABLE
HAZARDOUS DECOMPOSITION OR BY-PRODUCTS - CARBON MONOXIDE
CONDITIONS TO AVOID - TEMPERATURES OVER 400F MAY CAUSE RESIN
DEGRADATION
HAZARDOUS POLYMERIZATION - CANNOT OCCUR

## **SECTION VII - SPILL OR LEAK PROCEDURES**

 $\operatorname{SPILL}$  -  $\operatorname{SWEEP}$  UP MATERIAL TO PREVENT SLIPPING, ALLOW MOLTEN SPILLS TO COOL BEFORE SCRAPING UP AND DISPOSING.

WASTE DISPOSAL METHOD - IN ACCORDANCE WITH LOCAL REGULATIONS

## SECTION VIII - PROTECTIVE EQUIPMENT TO BE USED

VENTILATION - YES, PROVIDE ADEQUATE VENTILATION, DO NOT USE IN

CONFINED SPACES

PROTECTIVE GLOVES - YES EYE PROTECTION - YES

# **SECTION IX - PRECAUTIONS OR OTHER COMMENTS**

STORAGE AND HANDLING - STORE IN COOL DRY PLACE, OPTIMUM TEMPERATURE 70 F. PICK UP MATERIAL IMMEDIATELY TO ELIMINATE SLIPPING HAZARDS.