

Machete Operating Parameters

Diameter	RPM	Feed Rate
12"	1,900-2,300	5'-10' per minute
14"	1,650-2,000	5'-10' per minute
16"	1,450-1,800	5'-10' per minute
18"	1,300-1,600	5'-10' per minute
20"	1,200-1,450	5'-10' per minute